



Fluid Adjustment Knob


Top View



Bottom View



Air Inlet



Ink Inlet

All Dimensions In Inches

Tip Options

Cap Options

Tip Size

Diameter

Round Cap

Fan Cap

#0

0.021"

#1



0.028"

#2

0.04"

#3

0.046"



Carco Inc.

(313) 925-9000

10333 Shoemaker

Detroit, MI 48213

Model:

ES-370-JKT

Drawn By:

S. Walker

Date:

08-21-2023

1

2

3

4

5

6

7

8

A

B

C

D

E

F

G

H

J

K

Fluid Adjustment

ES- 370 -J-1

Top Cap Spring

ES- 370 -J-2

Body Shell Cap

ES- 370 -J-3

Piston Spring

ES- 370 -J-4

Piston

ES- 370 -J-5

Needle

ES- 370 -J-6

Fluid Body

ES- 370 -J-7

Needle Packing Assembly

ES-370-AP-3P

Fluid Body

ES- 370 -J-8

Round Tip









ES-370-T-0

Round Cap

ES-370-C-0

Tip Cap Nut

ES-370-AN



ES- 370 -JKT Repair Kit

Consists of



Qty:

1 ES-370-T-0 Tip

1 ES-370-C-0 Air Cap

1 ES-370-AP-3-P Needle Packing

1 ES- 370 -6 Needle

Tip Options		Cap Options	
Tip Size	Diamater	Round Cap	Fan Cap
#0	0.021"		
#1	0.028"		
#2	0.04"		
#3	0.046"		

Carco Inc.

10333 Shoemaker

Detroit, MI 48213

P: (313) 925-9000 | E: sales@carcousa.net

Model:	ES- 370 -JKT
Drawn By:	S. Walker
Date:	08-21-2023

1

2

3

4

5

6

7

22.0 x 17.0